

Mobile Hardbanding Services

Since 1976

**Serving all of Texas
South East New Mexico**

Featuring:

12 Mobile Hardband Units

A Mobile Grinder Unit

2 BHA Units

3 EMI Units

To: Our Hardband Clientele

Gentlemen,

We at Hardband Industries would like to say that we care how you spend your inspection and hardbanding dollar. Doesn't it make sense to spend that dollar with a vendor who can provide you with the high tech service that is required when working with inspection and hard metal application? A vendor who has the knowledge and expertise to survey your needs **BEFORE** he starts welding over previous hard metal applications! Spending your dollar in the proper avenue can save you thousands in potential drill pipe and drill collar repairs. Be advised, there are numerous products on the market for application in the hard metal industry, and you can be sure **NONE** of them blend with one another.

In summary, wouldn't you feel better entrusting a vendor that clearly has more experience and knowledge on this subject?

Give us a call and allow us to design the proper program for your inspection and hard metal needs.

Best Regards,

M.L. Spence
President
Hard Band Industries, Inc.



WHAT ARE YOU PAYING FOR EXACTLY?



COMPETITORS



INSPECTION

Drill Pipe


*EMI & BHA
Inspections*

*Qualified with
25 yrs.
experience*



**GRINDING SERVICES
FOR REMOVAL OF
IMPROPERLY APPLIED OR
NON-COMPATIBLE MATERIALS**





Why Spend Your Hardband Dollars With Us?

1. New - Custom Built - in our shop - well maintained equipment.
2. Long term operators with VAST experience & training.
3. Annual training, continual education from our hardband wire suppliers & manufacturers.
4. Consistent managerial observation of ALL jobs with respect to quality assurance, quality control.
5. 35 yeas experience - experts in tungsten carbide installation & compatibility of ALL casing friendly wires.





We now offer removal of Improperly Applied Hardband by way our Plasma Cutter:

Many times we see these problems in the field for the following reasons:

1. Incompatibility of two (or more) wires: Different products have different chemistry, therefore, they are not compatible with one another.
2. Re-application of Hardband too soon.

We have the knowledge and ability to avoid these situations **before** they occur. However, we see improperly applied Hardband on a regular basis. We now have the solution:

Mobile Plasma Cutter Removal





HARD BAND
INDUSTRIES, INC.

12200 County Road 129 West
Midland, Texas

P.O. Box 61528
Midland, Texas 79711

(800) 553-0096 • (432) 563-3752
Fax: (432) 563-3754

Travis Todd
Field Services Supervisor
(432) 661-5664
tjtodd75@gmail.com

Gary Whisenhunt
Inspection Division Manager
(432) 661-0341
gdwhisenhunt@gmail.com



Email: hardbandindustries@gmail.com
www.hardbandindustries.com

AVETTA
ISNET World
PEC/Premier Subscribers